OFFICE OF THE MARION COUNTY SURVEYOR SECTION RECORD CORNER SECTION 27 TOWNSHIP DATE: 8-16-07 PARTY CHIEF: Wilcoxen CREW: \_ Churchman Ave 3500 S TYPE OF MARKER: Harrison Emerson METHOD OF ESTABLISHMENT: \_\_\_\_County: 5-30-01 IN. S.P.C. E ZONE NAD '83 15042704 496121.3574(m) NAME: N: E: 64332.8551(m) 1. 5. 101 Churchman Avenue 3500 S 101.54, 5100 2. (PwP) Emerson 3.

Note: Two (2) brass plugs are located near this corner. One is 2.21' E and the second is 2.11'S of the corner and marks the P.C. at 140+53.73 "PR-1" according to sheet 11 on Project No. ST-40-001A. The other disc is 1.17' N and 0.17' E of the corner and was supposed to be located 2'+/- left of STA-140+56+/- "PR-1". This second disc was supposed to mark the quarter corner; however, it was apparently not set according to the highway plans. Re-tied 5-13-96 by Kiste. Re-tied 5-30-01 by Kiste. Re-tied 8-16-07 by Wilcoxen.

15	01	2	7	1	1
1	U4	_/_	1	V	4

	1504//	14
REF.	DISTANCE	DESCRIPTION
1.	76.11	Mag nail w/bw SF PwP#644 B 2"up
2.	101.54	Mag nail w/bw SW PwP#31-674 3"up
3.	94.27	Mag nail w/bw W PwP#671-674 3"up
4.	83.55'	Cut 'x' F bolt of signal pole base
5.	80.29'	Top nut of fire hydrant
6.	88.13'	Cut 'x' F bolt of signal pole base